

Spruce Creek Watershed Assessment and Stewardship Plan

**Center for Watershed Stewardship
Keystone Project 2003-2004
The Pennsylvania State University**

TABLE OF CONTENTS

List of Figures.....	iii
List of Tables.....	vi
List of Appendices.....	vii
Executive Summary.....	viii
Introduction.....	ix
Spruce Creek Team.....	x
Acknowledgements.....	xi
Watershed Assessment.....	xiii
Community Involvement and Concerns.....	xix
Stewardship Goals and Recommendations.....	xxi

Watershed Assessment

Chapter 1: Land Resources.....	1
Geography.....	2
Physiographic Setting.....	3
Topography.....	4
Geology.....	5
Soils.....	8
Land Cover.....	15
Chapter 2: Wildlife and Habitat.....	21
Habitat Types.....	22
Wildlife.....	24
Biological Health.....	30
Areas of Special Interest.....	31
Chapter 3: Surface Water.....	41
Stream Impairments.....	42
Biologic Indicators of Water Quality.....	44
Chemical Water Quality.....	49
Water Quality Simulation Modeling.....	53
Potential Source of Water Quality Impairments.....	59
Chapter 4: Groundwater.....	63
Karst Characteristics and Groundwater Recharge.....	64
Spring Discharges and Water Withdrawals.....	66
Drinking Water Supply.....	68
Source Water Protection Assessment.....	69
Sanitary Sewer and Septic Systems.....	70
Contamination.....	72

Chapter 5: Culture and Community.....81
History.....82
Public Space and Recreation.....95
Historic Preservation and Access to Public Land.....97
Demographics.....98
Transportation.....106
Planning Tools & Regulatory Controls.....107

Watershed Stewardship

Chapter 6: Public Involvement.....121
Chapter 7: Stewardship Goals & Recommendations.....125
Appendices.....165

Educational Disclaimer

The Pennsylvania State University in no way guarantees the work performed by students and makes no warranties, express or implied, regarding the quality of any product produced. Sponsor agrees to indemnify and hold harmless the University against any claims arising out of the Sponsor’s utilization, sale, or transfer of reports developed in whole or in part by students.

List of Figures

Chapter 1:

1.1 The Spruce Creek Watershed..... 2
1.2 The Ridge & Valley Physiographic Province..... 3
1.3 Elevation..... 4
1.4 Hypsometric Curve of the Spruce Creek Watershed..... 4
1.5 Slopes Map..... 5
1.6 Aspect Map..... 5
1.7 Geology Map..... 6
1.8 Timeline and Physical Descriptions of the Geologic Formations
(interpreted from Taylor, 1983)..... 7
1.9 Soil Association Map..... 9
1.10 Hagerstown-Hublersburg Soil Association..... 10
1.11 Morrison-Vanderlip Soil Association..... 10
1.12 Hazelton-Laidig-Buchanon Soil Association..... 11
1.13 Soil Capability Class Map..... 12
1.14 Distribution of Soil Capability Classes..... 12
1.15 Soil Capability Subclass Map..... 13
1.16 Distribution of Soil Capability Subclasses..... 13
1.17 Distribution of Land Cover Types Based on 1992 Satellite Imager..... 16
1.18 Forested and Non-forested Lands Interpreted from NLCD, 1992..... 16
1.19 Map of Parcels under 10 acres and Road Network as a Proxy of Developed Area
in the Watershed..... 17
1.20 Major public landholders in the Watershed..... 18

Chapter 2:

2.1 Vernal Pool (photo Rob Brooks)..... 22
2.2 Jefferson and Slimy Salamanders (photos enature.org)..... 23
2.3 National Wetland Inventory (NWI) Sites in the Spruce Creek Watershed..... 23
2.4 Ruffed Grouse (photo PA Game Commission)..... 25
2.5 Northern Copperhead (photo Ohio DNR)..... 26
2.6 Timber Rattlesnake (photo herpnet.net)..... 26
2.7 Angler Enjoying Spruce Creek (photo CWS)..... 26
2.8 Electrofishing Halfmoon Creek (photo CWS)..... 27
2.9 CWS Stream Monitoring Sites on Halfmoon Creek..... 27
2.10 Fish Identification and Measurement (photo CWS)..... 27
2.11 Fish Species Collected on Halfmoon Creek by Spruce Creek Keystone Team
(graphics Ted Walke PA Fish and Boat Commission)..... 28
2.12 GAP Analysis of Leading Landscapes in the Spruce Creek Watershed..... 29
2.13 Autumn Olive (photo CWS)..... 30
2.14 Purple Loosestrife (photo Gary Monroe USDA NRCS PLANTS Database)..... 30
2.15 Northern Saw-Whet Owl (photo John and Karen Hollingsworth canadianbiodiversity.org)..... 32

2.16 Biological Diversity Areas (BDAs) in the Spruce Creek Watershed.....33
 2.17 Eastern Small-footed Bat (photo enature.org).....34
 2.18 Serviceberry (photo Jim Stasz USDA-NRCS PLANTS Database).....36
 2.19 Torrey’s Rush (photo Larry Alain USDA-NRCS PLANTS Database).....37

Chapter 3:

3.1 Class A Wild Trout Streams. Source: PA Fish and Boat Commission, 2003.....42
 3.2 Waters Listed as Impaired by the Pennsylvania DEP. Source: PA DEP 2002.....43
 3.3 Other Water Quality Assessment Sites.....45
 3.4 CWS Monitoring Sites.....46
 3.5 Benthic Macroinvertebrate Sampling on Halfmoon Creek.....47
 3.6 Fish Community Sampling on Halfmoon Creek.....48
 3.7 Brown Trout from Halfmoon Creek.....48
 3.8 Stream Flow Monitoring.....51
 3.9 Total Suspended Solids.....52
 3.10 Total Phosphorus.....52
 3.11 Total Nitrogen.....53
 3.12 Monthly Erosion and Sediment Loading.....55
 3.13 Sources of Erosion and Sediment.....56
 3.14 Monthly Nutrient Loading.....56
 3.15 Phosphorus Contribution by Source.....57
 3.16 Nitrogen Contribution by Source.....57
 3.17 Contribution Areas.....57
 3.18 Observed and Predicted Mean Annual Phosphorus Loads.....58
 3.19 Observed and Predicted Mean Annual Nitrogen Loads.....58

Chapter 4:

4.1 “Sinkhole formation” (painted by Karen Carr).....64
 4.2 Approximate Groundwater Divide and Direction of Groundwater Flow
 Between the Spruce Creek and Spring Creek Watersheds.....65
 4.3 Public Water Wells in the Spruce Creek Watershed.....67
 4.4 Wells and Springs of the Spruce Creek Watershed
 (interpreted from PA Geological Survey 2000).....68
 4.5 Example of Wellhead Protection Zones.....70
 4.6 Septic Suitability of Soils within the Spruce Creek Watershed.....73
 4.7 Percentage of Wells Sampled with Bacterial Contamination in the Lower Susquehanna
 River Basin Tabulated from Data Published in Bickford et al. (1996).....74

Chapter 5:

5.1 Centre County 1882.....83
 5.2 Huntingdon Furnace Stack.....84
 5.3 Huntingdon Furnace 1968 (Elizabeth Nearhoof).....84

5.4	Ruins of Old Iron Furnace, Centre County Historical Society.....	85
5.5	Pennsylvania Furnace 1968 with Historic Remains (Elizabeth Nearhoof).....	85
5.6	Scotia Iron Works, <i>The Story of Scotia</i> (Harry Williams).....	86
5.7	Scotia Ore Mines 1892, <i>The Story of Scotia</i> (Harry Williams).....	87
5.8	Remains of the Ditches of the Washer.....	87
5.9	Sketched Maps of Tow Hill (Ernest Harpster).....	88
5.10	The “Big Lake” at Tow Hill.....	89
5.11	Iron Ore Mines.....	89
5.12	Train Schedule, November 8, 1880 (Pennsylvania Railroad Museum Library).....	91
5.13	Centre County Railroad Map, 1910.....	91
5.14	Logging Railroad Map (Hewitt McNitt Lumber Company).....	92
5.15	A Late 1700s Stone House near Colerain Picnic Area.....	93
5.16	Pennsylvania Furnace Mansion	93
5.17	Huntingdon Furnace Mansion.....	93
5.18	Colerain Forges Mansion.....	94
5.19	Huntingdon Furnace Grist Mill.....	94
5.20	Upper Spruce Creek Presbyterian Church, 1858.....	95
5.21	Scotia Shooting Range.....	95
5.22	Biking Route (BikePA.com).....	96
5.23	Bird’s-eye View of Colerain Area from Colerain Road.....	97
5.24	Camp Kanesatake.....	97
5.25	Population Growth in Watershed Municipalities, 1930 to 2000.....	99
5.26	Age Groups for All Watershed Municipalities, 2000.....	101
5.27	Housing Type, Occupied or Vacant, in Watershed Municipalities, 2000.....	102
5.28	Educational Attainment of Watershed Residents, 2000.....	102
5.29	Percent of Workforce by Industry for Watershed and Municipalities, 2000.....	104
5.30	Percent Civil Labor Force Unemployed, 2000.....	105
5.31	Innovation Corridor Billboard.....	106
5.32	Regional Growth Boundary.....	108
5.33	Zoning Map.....	109
5.34	Prime Agricultural Soils.....	114
5.35	Agriculture Security Area Map.....	115

Chapter 6:

6.1	Fall 2003 Public Meeting Warriors Mark Township (photo CWS).....	122
6.2	Residents prioritizing issues at February 2004 Meeting (photo CWS).....	122
6.3	March 2004 Planning Meeting (photo CWS).....	124

Chapter 7:

7.1	Schematic of Ideal Riparian Buffer Design and the Benefits They Can Provide (National Agroforestry Center 1997).....	126
7.2	Example of an Unhealthy Riparian Buffer.....	127
7.3	Example of a More Healthy Riparian Buffer.....	127

List of Tables

Chapter 1:

1.1 Subwatershed Characteristics.....3
 1.2 Slope Distributions.....5
 1.3 Rock Type Distributions in the Watershed.....6
 1.4 Distribution of Soil Associations.....9
 1.5 Soil Capability Classes and Subclasses (interpreted from Merkle, 1978).....11
 1.6 Climate Data for State College, PA14
 1.7 Climate Data for Huntingdon, PA.....15

Chapter 2:

2.1 Amphibians and Reptiles in the Spruce Creek Watershed.....25
 2.2 Fish Species Data of Halfmoon Creek.....27
 2.3 Biological Diversity Areas in the Spruce Creek Watershed.....32

Chapter 3:

3.1 Halfmoon Creek IBI Scores.....49
 3.2 Predicted Monthly Loads.....54
 3.3 Loads by Source.....55

Chapter 4:

4.1 Municipal Water Suppliers in the Watershed [Information from U.S. EPA (2004c)].....69
 4.2 Date of Adoption of Act 537 Plans by Watershed Municipalities.....71

Chapter 5:

5.1 National Register Listed or Eligible Properties in the Spruce Creek Watershed.....93
 5.2 Population and Rate of Change in Centre and Huntingdon Counties, 1900 to 2000.....99
 5.3 Population and Rate of Change in Watershed Municipalities, 1930 to 2000.....99
 5.4 Population Density per Square Mile in Watershed Municipalities, 1996 and 2000.....100
 5.5 Population Projections for the Watershed Municipalities.....100
 5.6 Median Household and Family Incomes in Watershed Municipalities, 2000.....100
 5.7 Poverty Rate in Watershed Municipalities, 2000.....101
 5.8 Percent of Workforce by Occupation for Watershed and Municipalities, 2000105
 5.9 Plans and Ordinances Developed, or Currently Under
 Development, by Watershed Municipalities.....107

Chapter 6:

6.1 Community Prioritization of Issues.....123

List of Appendices

Chapter 1:

None

Chapter 2:

2A: Species Names.....166
2B: Fish Species Collected on Halfmoon Creek by Keystone Team (Fall 2003).....172
2C: Species and Biological Diversity Areas.....173
2D: Federal and State Endangered Species Categories / Global and State Ranks.....174

Chapter 3:

3A: Existing Macroinvertebrate and Habitat Data Collected by PA Fish and Boat Commission.....177
3B: Macroinvertebrate and Habitat Data Collected at Six Stations on Halfmoon Creek by the Center for Watershed Stewardship in Fall 2003.....180
3C: Fish IBI Scoring and Metric Descriptions (adapted from Daniels et al. 2002).....187
3D: Water Quality Parameters.....189
3E: Existing Water Quality Data from Other Sources.....196
3F: Water Quality Data Collected by the Center for Watershed Stewardship.....198

Chapter 4:

None

Chapter 5:

5A: Iron Ore Banks, Spruce Creek Watershed.....205
5B: Lewisburg and Tyrone Railroad Train Schedule, May 17, 1897 (Pennsylvania Railroad Museum Library).....206
5C: Bellefonte Central Railroad Train Schedule, Apr 3, 1899 (Pennsylvania Railroad Museum Library).....206
5D: GIS Mapping of Historic Buildings, Spruce Creek Watershed.....207
5E: GIS Mapping of Historic Buildings, Pennsylvania Furnace.....208
5F: GIS Mapping of Historic Buildings, Huntingdon Furnace.....209
5G: Zoning District Summaries for Ferguson Township.....210
5H: Zoning District Summaries for Halfmoon Township.....211

Chapter 6:

6A: Results of County and Municipality Surveys Summarized.....212

Chapter 7:

None